Just some places to attach your
measuremt equipment to the board.
Corespontences with MEASUREMENT_POINT_ROUND_REVE_DATE15JUN2010 and
MEASUREMENT_POINT_SQUARE_REVE_DATE15JUN2010 from the library
SymbolsSimilarEN60617+oldDIN617-RevE4.
Despite it is not a EN60617 Symbol, it may be useful.

*For suggestions
and improvements
please contact
me at
bernd.wiebus@gmx.de*

MP
Measurement_Point_Round-SMD-Pad_Big

MP
Measurement_Point_Square-SMD-Pad_Big

MP
Measurement_Point_Round-SMD-Pad_Small

MP
Measurement_Point_Square-SMD-Pad_Small

MP
Measurement_Point_Round-TH_Big

MP
Measurement_Point_Square-TH_Big

MP
Measurement_Point_Round-TH_Small

MP
Measurement_Point_Square-TH_Small

1:1 Print! Check dimension by controlling the gauge!

KiCAD Footprints of some measurement points from the file
Measurement_Point_RevA.mod
Author: Bernd Wiebus / Uedem / Germany / 21 Jun 2010

File: Measurement_Point_RevA.kicad_pcb
Sheet:
Title:
Size: A4   Date: Rev:
KiCad E.D.A.   Id: 1/1