MSC

Gauge_10mm_Type1_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_10mm_Type2_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_10mm_Type3_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_10mm_Type4_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_10mm_Type5_SilkScreenTop_RevA_Date22Jun2010



MSC

Gauge_50mm_Type2_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_100mm_Type2_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_50mm_Type1_SilkScreenTop_RevA_Date22Jun2010

MSC

Gauge_100mm_Type1_SilkScreenTop_RevA_Date22Jun2010

Whereever you want to add a metric scala to your board.
For different purposes, as an example to control the dimensions of your print out.
Correspondences with DUMMY_MEASUREMENT-SCALE_REVE_DATE15JUN2010 from SymbolsSimilarEN60617+oldDIN617-RevE4.lib. Just to get schematic and board consistent.

1:1 Print! Check dimension by controlling the gauge!

KiCAD Footprints of some measurement scalas from the file Measurement-Scala_RevA.mod

Author: Bernd Wiebus / Uedem / Germany / 02 Jul 2010

For suggestions and improvements please contact me at bernd.wiebus@gmx.de

Licence: CC-Zero / Public Domain
NO RESTRICTION ! NO WARRANTY!
http://creativecommons.org/

File: Measurement-Scala_RevA.kicad_pcb		
Sheet:		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A.		Id: 1/1