L

Neosid_Air-Coil_SML_2turn_HAM0231A

L

Neosid_Air-Coil_SML_1turn_HDM0131A

L

Neosid_Air-Coil_SML_3turn_HAM0331A

L

Neosid_Air-Coil_SML_2turn_HDM0231A

L

Neosid_Air-Coil_SML_4turn_HAM0431A

L

Neosid_Air-Coil_SML_3turn_HDM0331A

L

Neosid_Air-Coil_SML_5turn_HAM0531A

L

Neosid_Air-Coil_SML_4turn_HDM0431A

L

Neosid_Air-Coil_SML_6turn_HAM0631A

L

Neosid_Air-Coil_SML_5turn_HDM0531A

L

Neosid_Air-Coil_SML_6turn-10turn_HAM0631A-HAM1031A

L

Neosid_Air-Coil_SML_6-10turn_HDM0431A-HDM1031A

100 mm

90

80

70

60

50

40

30

20

10 mm

5

0

0 5 10   20   30   40   50   60   70   80   90   100mm

1:1 Print! Check dimension by controlling the gauge!

KiCAD Footprints of some NEOSID air-coils from the file
Neosid_Air-Coil_SML_HAMxx31A_HDMxx31A_RevA_25Apr2012.mod
Author: Bernd Wiebus / Uedem / Germany / 25 April 2012

For suggestions
and improvements
please contact
me at
bernd.wiebus@gmx.de