


Nebelmaschine-V1_2

14.11.20 12:14

Sheet: 1/1



Nebelmaschine-V1_2
 14.11.20 12:14
 Sheet: 1/1

1 1 2 2 3 3 4 4 5 5 6 6

1 1 2 2 3 3 4 4 5 5 6 6

A

B

C


D

In series to supply and lamp

In series to supply and lamp


Moc3043 Zero crossing

Channel phase control signal input





High voltage side!

Channel phase control signal input



High voltage side!



1

2

3

4

5

6

Nebelmaschine-V1_2

14.11.20 12:14

Sheet: 1/1

A

B

C

D