


Just some places to attach your measurement equipment to the board. Correspondences with MEASUREMENT_POINT_ROUND_REVE_DATE15JUN2010 and MEASUREMENT_POINT_SQUARE_REVE_DATE15JUN2010 from the library SymbolsSimilarEN60617+oldIN617-RevE4. Despite it is not a EN60617 Symbol, it may be useful.



1:1 Print! Check dimension by controlling the gauge!

KiCAD Footprints of some measurement points from the file Measurement_Point_RevA.mod



Author: Bernd Wiebus / Uedem / Germany / 21 Jun 2010
GNU-GPL NO WARRANTY!

File: Measurement_Point_RevA.brd	
Sheet: 1/1	
Title:	
Size: A4	Date: 13 apr 2011
KiCad E.D.A. pcbnew (2011-03-30 BZR 2932)-stable	
Rev:	Id: 1/1